SAU-56 Somersworth School District

.0	CATION OF WORK	WRITTEN BY:	APPROVED BY:	DATE	LAST REVISION
	All Schools	Karl Ingoldsby	Somersworth School District JLMC	3/4/2020	New
	POTENTIAL HAZA	RDS	ERSONAL PROTECTIN EQUIPMENT (PPE) oves, chemical goggles or	RECO	ADDITIONAL COMENDATIONS se training
•	Surfaces causing falls, v Chemicals – mixing, pou Explosion if near flamma material / vapors	uring shi	eld when handling chemic supplier or material label	cals as • Closed	toe shoes, non-slip d Fall prevention
			eletal injury (MSI) can inc nt or strength in a body pa		
	namonoo, anging, an		E WORK PROCEDURI		
No	te: This procedure is for				
۹.			damage. Do not use a da	amaged machine an	d notify your supervisor
3.	Place out caution signs and barricades required in work area(s)				
	Get help to move large or heavy objects or furniture. Remember to try to keep your back straight and use your weight to help slide objects rather than using only your arms. If lifting, bend and push through your legs. Communicate the timing for the lift if lifting with another worker				
D.	For stripping / cleaning floors:				
E.	Mix chemical with water slowly in a bucket according to label or put hose into tank to fill and then add cleaning product. If using a bucket, only fill it ³ / ₄ full to reduce spills. Pour mixture into the machine's tank slowly to avoid spilling. Know where to find the MSDS sheets in the event of a chemical accident or spill.				
F.	Before starting a ride on machine, stand on the pedal platform				
G.	When operating the floor machine, be cautious of any grades as this can increase the risks for tipping or having the machine become stuck or travelling too fast. Do not operate scrubber mechanisms on grades over 2% and do not travel with scrubber on grades over 10% or as per manufacturer guidelines				
H.	Be cautious when stepping from machine onto floor, as the floors may be slippery form the fluid				
l .	Before leaving, servicing or charging, stop the machine on a level surface, turn it off, apply parking brake and remove the key				
		BEGI	ILATORY REQUIREM	ENTS	
	uipment Manual os, Trips, and Falls trai			<u> 1115</u>	